








# BORGÅSEN




Design and Quality  
IKEA of Sweden






130646

4x



105107

8x




BRG010

6x



BRG005

2x




BRG006

2x




BRG007

2x




BRG008

4x




120202

1x




100092

1x




BRG001

2x




BRG002

2x




100712

4x




100854

4x




BRG009

2x



BRG003


2x




BRG004

10x


1






2




3








7




8





9






10















12




13




14




15




# 16




# 17







18




19










12




13







14




15




16



17



18



19

